


Existing Conditions



Existing lobby area



Plaster damage and cracking in outdoor vestibule



Plaster deterioration in the Grand



Plaster deterioration in Mezzanine Lobby Floors



















